



DIVISION OF OIL, GAS & MINING

February 19, 1982

Thomas N. Tetting
Division of Oil, Gas and Mining
4241 State Office Building
Salt Lake City, Utah 84114

Re: Annual Report and updated surface map for Rim Columbus ACT/037/006

Dear Tom:

Enclosed is the annual report for the Rim Columbus Mine and an updated surface map to replace maps number 1 and number RC-T-97e. Map number 1 was submitted October 18, 1976 with the original mining and reclamation plan. Map number 2, also submitted at that time is still current.

Map number RC-T-97e has been submitted twice, the first time for an amendment on January 26, 1978. The vent hole on map number RC-T-29e submitted along with that amendment has not been put in yet, however it is still in the mine plan and we wish to keep that map current.

An updated copy of map number RC-T-97e was also submitted on June 18, 1981 with an amendment for a water treatment facility. The enclosed map will replace that map as well.

I have also recalculated the disturbed acreage figures in an attempt to bring everything up to date, and they are catagorized on the attached sheet. If you have any questions please don't hesitate to contact me.

Respectfully,

Ricky J. Broschat/ Reclamation Scientist

ATLAS MINERALS DISTURBED ACREAGE ACT/037/006

	RIM	COLUMBUS	HUMBUG	TOTAL
Mining	8.31	2.2	1.8	12.31
Roads	1.73			1.73
Ponds	1.38			1.38
Vent Hole (Proposed)	(0.94)			0.94
			ТОТ	AL <u>16.36</u>